

BC66-NA Release Notes

NB-IoT Module Series

Rev. BC66-NA _Firmware_Release_Notes_V0201_01.002.01.002

Date: 2022-03-23



Our aim is to provide customers with timely and comprehensive service. For any assistance, please contact our company headquarters:

Quectel Wireless Solutions Co., Ltd.

Building 5, Shanghai Business Park Phase III (Area B), No.1016 Tianlin Road, Minhang District, Shanghai 200233, China

Tel: +86 21 5108 6236

Email: info@quectel.com

Or our local office. For more information, please visit:

<http://www.quectel.com/support/sales.htm>.

For technical support, or to report documentation errors, please visit:

<http://www.quectel.com/support/technical.htm>

Or email to support@quectel.com.

Disclaimer

While Quectel has made efforts to assure the accuracy of this document, unless otherwise provided by valid agreement, Quectel assumes no liability resulting from any inaccuracies or omissions in this document, or from use of the information obtained herein. Quectel reserves the right to make changes to any contents described herein and reserves the right to revise this document and to make changes from time to time in content hereof with no obligation to notify any person of revisions or changes. Before using any updated software, please read this statement carefully. By accessing or using the said software you irrevocably and unconditionally accept and confirm that you agree to be bound by this statement. In the event you disagree with any provision hereof and would not like to be bound by this statement you shall cease use of the said software immediately.

Duty of Confidentiality

The Receiving Party shall keep confidential all documentation and information provided by Quectel, except when the specific permission has been granted by Quectel. The Receiving Party shall not access or use Quectel's documentation and information for any purpose except as expressly provided herein. Furthermore, the Receiving Party shall not disclose any of the Quectel's documentation and information to any third party without the prior written consent by Quectel. For any noncompliance to the above requirements, unauthorized use, or other illegal or malicious use of the documentation and information, Quectel will reserve the right to take legal action.

Copyright

The information contained here is proprietary technical information of Quectel Wireless Solutions Co., Ltd. Transmitting, reproducing, disseminating and editing this document as well as using the content without permission are forbidden. Offenders will be held liable for payment of damages. All rights are reserved in the event of a patent grant or registration of a utility model or design.

Copyright © Quectel Wireless Solutions Co., Ltd. 2022. All rights reserved.

1. Preamble

This document provides the Release Notes for BC66-NA firmware version **BC66NADAR02A01_01.002.01.002**. It describes major changes compared to BC66-NA firmware version **BC66NADAR02A01_01.001.01.001**.

2. Matters Needing Attention

SN	Brief Description
1	Need special downloading tool (contact Quectel to retrieve) to upgrade the module firmware from BC66NADAR01A01 to BC66NADAR02A01_01.00x.01.00x .
2	Not support DFOTA between BC66NADAR01A01 and BC66NADAR02A01_01.00x.01.00x .
3	Due to the limitation of testing environment, only the basic NIDD data exchange is supported and verified, not recommend to mass production integration.
4	Due to the limitation of testing environment, AT+QBANDPC is only tested the basic function, need to be verified in the actual real network.
5	Not support carrier certification.

3. New Features

Item /Category	Brief Description	Since
GENERAL	Added Module PIN 8 as deep sleep indication GPIO in Standard Firmware Mode.	R01A01
GENERAL	Added AT+QPOWD=2 to reset the module after OK is returned.	R01A01
GENERAL	Added AT+QPOWD=1 to force module power down.	R01A01
GENERAL	Added AT+QADC command for ADC sampling via ADC0 channel.	R01A01
GENERAL	Added AT+QVBATT command for UNDER VOLTAGE/OVER VOLTAGE warning and protection.	R01A01
GENERAL	Added AT+QCFG="vbattimes" command to configure the measurement interval of AT+QVBATT .	R01A01
GENERAL	Added AT+QCFG="activetimer" command to configure whether to use the value of active timer (T3324).	R01A01
GENERAL	Added URC RI mask option to AT+QCFG command.	R01A01

GENERAL	Optimized DNS feature. Put the DNS resolution result to RETSRAM and the DNS resolution will not be restarted until the TTL expires.	R01A01
NETWORK	Added AT+QBANDSL command for band priority selection.	R01A01
NETWORK	Added combine attach/up/upopt/multidrb options to AT+QCFG command.	R01A01
NETWORK	Added AT+QIPADDR command to query the whole module IP addresses.	R01A01
QuecOpen	Added QI_PowerDown API for power down the module in QuecOpen.	R01A01
QuecOpen	Added QI_vsprintf and QI_vsnprintf API for flexibility format control.	R01A01
QuecOpen	Added FreeRTOS API in QuecOpen.	R01A01
QuecOpen	Added TCP/UDP Socket API in QuecOpen.	R01A01
QuecOpen	Added SSL/TLS support in QuecOpen.	R01A01
QuecOpen	Added QI_GetPowerVol API in QuecOpen for obtain current power supply voltage.	R01A01
QuecOpen	Added API in QuecOpen for deep sleep event callback register.	R01A01
QuecOpen	Added Hardware flow for UART1 in QuecOpen.	R01A01
LwM2M	Added the DTLS Resumption function. The goal of this feature is to reduce the amount of data interaction between the module and server after the deep sleep wakes up and to be more protocol compliant.	R01A01
LwM2M	Added a mechanism that module will automatically register to T-Mobile LwM2M server when the module use T-Mobile 's USIM card for T-Mobile certification.	R01A01
LwM2M	Added AT+QLWCFG="lifetime_enable" command to enable/disable automatic lifetime update (enabled in default).	R01A01
LwM2M	Added AT+QLWCFG="dtls_mode",<mode> command to configure the DTLS scheme(DTLS resumption scheme is used in default).	R01A01
LwM2M	Added AT+QLWCFG="recovery_mode",<mode> command to control whether the module automatically recovers from deep sleep. The AT+QLWRECOVER command is used to trigger module's recovery logic when the manual recover mode is enabled.	R01A01
LwM2M	Added AT+QLWCFG="dtls_version",<version> command to configure the DTLS version to be used (negotiate with the server adaptively in default).	R01A01

LwM2M	Added the URC of +QLWURC: "lw_event" to indicate whether the module received the server RST message of LwM2M.	R01A01
LwM2M	Added AT+QLWCFG="retransmit_mode" command to configure the retransmission policy (interval double/ interval consistent).	R01A01
LwM2M	Changed the range value of the retrans_max_times parameter of AT+QLWCFG="retransmit" command (0-8), and there will be no retransmission for CON data when it set to 0.	R01A01
SSL/TLS	Supported SSL 3.0.	R01A01
SSL/TLS	Added AT+QSSLCFG=(1-3),(0-5),"sslversion" command to support module protocol version selection.	R01A01
MQTT	Added MQTT over IPV6.	R01A01
TCP/IP)	Added ping over IPV6 via AT+QPING .	R01A01
GENERAL	Upgrade the chip code version to the newest baseline. (1) Optimized the performance of SMS. (2) Optimized the performance of NIDD. (3) Optimized the band searching mechanism for searching the best suitable cell to camp on. (4) Optimized the performance of R14 features. (5) Improved the stability of PPP feature.	R02A01_01.0 01.01.001
GENERAL	Added query mode for AT+QNBIOTEVENT command to query the current PSM indication setting.	R02A01_01.0 01.01.001
NETWORK	Added AT+QEMMTIMER command to enable/disable the URC reporting of back-off timer.	R02A01_01.0 01.01.001
NETWORK	Added AT+QBANDPC command to control the transmitter power class.	R02A01_01.0 01.01.001
NETWORK	Added AT+QENG=3 command to query the current PLMN information.	R02A01_01.0 01.01.001
NETWORK	Added AT+QLOCKF=2 command to set preferred EARFCN list.	R02A01_01.0 01.01.001
NETWORK	Added basic NIDD(Non-IP Data Delivery) data exchange AT commands.	R02A01_01.0 01.01.001
QuecOpen	Added more power on reason information for QI_GetPowerOnReason API.	R02A01_01.0 01.01.001
QuecOpen	Added force power off and reset option for QI_PowerDown API.	R02A01_01.0 01.01.001
TCP	Added support for TCP LISTENER feature.	R02A01_01.0 01.01.001
UDP	Added support for UDP SERVER feature.	R02A01_01.0 01.01.001
LwM2M	Added the default instance response data format configuration option for AT+QLWCFG="def_inst_rsp_data_format" command.	R02A01_01.0 01.01.001

LwM2M	Added support for Object 3 resource 14(3/0/14) which can read/write UTC offset and resource 15(3/0/15) which can read/write timezone feature.	R02A01_01.0 01.01.001
SSL/TLS	Added AT+QSSLCFG=<contextID>,<connectID>,"sni" to support server name indication feature.	R02A01_01.0 01.01.001
COAP	Added feature of CoAP and CoAPS.	R02A01_01.0 02.01.002
DFOTA	Added support for HTTPS DFOTA.	R02A01_01.0 02.01.002
DFOTA	Added IPv6 support for AT+QFOTADL command.	R02A01_01.0 02.01.002
HTTP/HTTPS	Added feature of HTTP and HTTPS.	R02A01_01.0 02.01.002
LwM2M	Added configurable support for OMA object-instance-resource(3/0/3) via AT+QLWCFG="CR" command.	R02A01_01.0 02.01.002
LwM2M	Added AT+QLWCFG="dtls_lifetime" command to set the elapse time for the next DTLS re-handshake to reduce the impact of NAT port mapping on DTLS connection.	R02A01_01.0 02.01.002
LwM2M	Added the TLS_PSK_WITH_AES_128_CCM_8 cipher suite for LwM2M DTLS connection.	R02A01_01.0 02.01.002
NETWORK	Added AT+QOOSAIND command to enable/disable the OOS URC indication report.	R02A01_01.0 02.01.002
GENERAL	Added AT+QFLASHR command to read flash data from FOTA temp area.	R02A01_01.0 02.01.002

4. Improved Features

Item/Category	Brief Description	Since
LwM2M	Fixed the bug that observed option count can't be incremented after entering deep sleep.	R01A01
LwM2M	Fixed the bug that the command result of AT+QLWCONFIG? displays an incorrectly formatted issue.	R01A01
LwM2M	Optimized the LwM2M NVDM management mechanism to reduce the erase frequency of LwM2M operations.	R01A01
LwM2M	Decreased the maximum number of observe information that module can save from 20 to 10.	R01A01
GENERAL	Fixed the bug that NETLIGHT blink frequency is not accurate.	R01A01
GENERAL	Optimized the implementation of AT+QSCLK=1 to release all the known AP locks for quick sleep control.	R01A01

GENERAL	Fixed the bug that ADC sampling is not accurate when the divider resistor is too high.	R01A01
GENERAL	Fixed the bug that RI pin abnormal hopping when module power on, reboot or deep sleep wakeup.	R01A01
GENERAL	Optimized DNS resolution retransmission interval and times.	R01A01
GENERAL	Optimized the default configuration of DNS server.	R01A01
NTP	Fixed the bug that NTP port is always fixed to 123 and can't configure issue.	R01A01
MQTTS	Fixed the bug that module will low probability abnormal reboot when the SSL/TLS session is closed by the remote MQTTS server.	R01A01
MQTT	Fixed the bug that module will low probability crash when perform MQTT connect operation frequently.	R01A01
TCP(IP)	Fixed the bug that TCP/UDP over IPV6 domain mode can't work properly via AT+QIOPEN .	R01A01
TCP(IP)	Fixed the bug that DNS query result is displayed blank or wrong format via AT+QIDNSCFG=1 .	R01A01
TCP(IP)	Fixed the bug that the port dedicated by AT+QIOPEN is not corresponding to the actually sending port in UDP IPV6 mode.	R01A01
SSL/TLS	Fixed the bug that the sending data will be truncated when HEX 0x00 is contained in the payload.	R01A01
SSL/TLS	Fixed the bug that the module will low probability crash when close the SSL/TLS session for multitask synchronization issue.	R01A01
SSL/TLS	Fixed the bug that AT+QSSLCFG? return wrong result when multiple sockets are established.	R01A01
SSL/TLS	Optimized the implementation of AT+QSSSEND , And it is recommended that MCU post-input data in 500ms delay after '>' is received.	R01A01
NETWORK	Fixed the bug that module is abnormal wakeup which is triggered by poll interval mechanism in eSIM.	R01A01
NETWORK	Fixed the bug that module is abnormal wakeup due to bug in "periodic attempts may be postponed while the MS is in power saving mode".	R01A01
NETWORK	Fixed the bug that abnormal TAU is triggered after module exit PSM mode.	R01A01
NETWORK	Fixed the bug that SIM initialization fails when binary record length is exceeds 255 bytes which cause module can't register to network.	R01A01
NETWORK	Fixed the bug that PAP authentication failed in real network.	R01A01
QuecOpen	Changed the support ADC sampling channels from 4chs to 3chs.	R01A01
QuecOpen	Fixed the bug that GPIO input level is reverse in input mode when set to pull-up or pull-down.	R01A01

QuecOpen	Fixed the bug that module will low possibility stuck when executes AT+CGATT command.	R01A01
QuecOpen	Optimized timer management implementation.	R01A01
QuecOpen	Fixed the bug that the DFOTA result URC will low probability not reported to APP .	R01A01
GENERAL	Fixed the bug that the URC RI hopping is abnormal in light sleep scenario.	R02A01_01.0 01.01.001
GENERAL	Fixed the bug that when the module is in the connected state and execute AT+COPS command to trigger the manual search, the module will get stuck and cannot process subsequent AT commands.	R02A01_01.0 01.01.001
QuecOpen	Fixed the bug that the URC low probability can't reported when executing MQTT CLOSE and DISC operation via RIL API.	R02A01_01.0 01.01.001
QuecOpen	Fixed the bug that CS line is abnormal released to high state in the last clock cycle during hardware SPI data processing.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that module will crash when illegal EPS NAS Security Context exists in SIM.	R02A01_01.0 01.01.001
NETWORK	Optimize the logic upon receiving Cause Code #17 in EMM procedure.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that module will crash when validity check of GUTI failed.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that the CEL value keeps same even network coverage changed in IDLE mode.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that the query result of AT+CGATT? is zero when module successfully registers to the network in combined attach mode.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that the module would not send TAU again upon receiving Paging when the timer T3346 is running.	R02A01_01.0 01.01.001
NETWORK	Optimized EARFCN storing mechanism. Module will save the EARFCN with PLMN information when entering ILDE mode after registered the network.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that module low probability can't initiate network searching process after deep sleep wakeup.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that data uplink failed when TAU reject event occurs.	R02A01_01.0 01.01.001
NETWORK	Fixed the bug that module low probability crash when performing attach procedure.	R02A01_01.0 01.01.001
LwM2M	Fixed the bug that wrong query status returned via AT+QLWSTATUS? after the module wakes up from deep sleep.	R02A01_01.0 01.01.001
LwM2M	Optimized the number of observed resources from 10 to 6 after wake up from deep sleep.	R02A01_01.0 01.01.001
LwM2M	Fixed the bug that the module performs the update operation during the de-registration process, which will cause the underlying	R02A01_01.0 01.01.001

	LwM2M status becomes abnormal.	
LwM2M	Fixed the bug that the module doesn't send registration packet after the DNS resolution is successful in the IPv6 domain mode, connecting to a non-encrypted server scenario.	R02A01_01.0 01.01.001
LwM2M	Fixed the bug that module can't enter deep sleep quickly when the automatic update fail after wake up from deep sleep.	R02A01_01.0 01.01.001
DNS	Optimized DNS resolution mechanism in reboot/deep sleep wakeup/retransmission phase.	R02A01_01.0 01.01.001
UDP	Fixed the bug that the configuration UDP port via AT+QIOPEN command is not take effect in IPv6 scenario and deep sleep wakeup scenario.	R02A01_01.0 01.01.001
UDP	Fixed the bug that UDP session becomes invalid when wake up from deep sleep mode in IPv6 scenario.	R02A01_01.0 01.01.001
MQTT	Fixed the bug that downlink data is lost when the total length of URC string exceeds 1400 bytes. Now changed to multiple packets reporting via URC.	R02A01_01.0 01.01.001
MQTT	Fixed the bug that JSON format data is not supported by AT+QMTCFG command.	R02A01_01.0 01.01.001
MQTT	Enlarged the receive buffer from 2KB to 6KB to fix the bug that module can't process data which is larger than 2KB.	R02A01_01.0 01.01.001
SSL/TLS	Enlarged the SSL RX buffer size to 16KB to fix the bug that module can't buffer the certification completely due to a small RX buffer.	R02A01_01.0 01.01.001
DFOTA	Fixed the bug that the module has probability auto-establish an unexpected PDN session after deepsleep wakeup.	R02A01_01.0 02.01.002
GENERAL	Fixed the bug that the module will crash when file size of EPSLOC1 in SIM card is not in accordance with the spec.	R02A01_01.0 02.01.002
MQTT	Fixed the bug that module crash occurs when received data payload exceeds 3K bytes in hex mode.	R02A01_01.0 02.01.002
MQTT	Fixed the bug that module will low probability crash due to the overflow of TCP buffer in poor network condition.	R02A01_01.0 02.01.002
MQTT	Fixed the bug that the module failed to connect to the Azure IoT platform by using the unauthenticated encryption mode.	R02A01_01.0 02.01.002
MQTT	Fixed the bug that module will low probability send two MQTT keep-alive packets at the same time which will result in the disconnection of currently MQTT session.	R02A01_01.0 02.01.002
NETWORK	Fixed the bug that the RAI behavior is not work as expected due to VZW required logic, now change the logic binding to VZW SIM.	R02A01_01.0 02.01.002
NETWORK	Removed the instantly URC reports of +CEREG: 2 after the module wakes up from PSM.	R02A01_01.0 02.01.002
NETWORK	Fixed the bug that the module does not perform the attach procedure after the back-off timer is timeout.	R02A01_01.0 02.01.002
NETWORK	Fixed the bug that ERROR is returned when executing AT+CPSMS command to disable T3412_EXT timer.	R02A01_01.0 02.01.002

NETWORK	Fixed the bug that the module will crash when AT+COPS=2 command is executed in PSM mode due to the conflict of PSM wakeup searching and manual de-register procedure.	R02A01_01.0 02.01.002
QuecOpen	Fixed the bug that the RIL interface cannot receive "OK" return code in data mode.	R02A01_01.0 02.01.002
QuecOpen	Fixed the bug that the asynchronous result codes can not report to QuecOPEN layer when MQTT/SSL RIL APIs are used.	R02A01_01.0 02.01.002
QuecOpen	Fixed the bug that module will low possibility stuck when executes AT+CGATT command in QuecOpen.	R02A01_01.0 02.01.002
QuecOpen	Fixed the bug that the QI_IIC_Write_Read interface can't read multiple bytes in one shot.	R02A01_01.0 02.01.002
SSL/TLS	Fixed the bug that module can not read all received data out in one shot in subcontracting scenario.	R02A01_01.0 02.01.002
TCPUDP	Fixed the bug that wrong TCP acked result returned by using AT+QISEND=0,0 command in IPv6 scenario.	R02A01_01.0 02.01.002
TCPUDP	Fixed the bug that the inputted data with "1A" character ending can't be echoed in the data mode.	R02A01_01.0 02.01.002
TCPUDP	Fixed the bug that module will probability fail to establish an TCP session after reboot due to same local port is used internally.	R02A01_01.0 02.01.002

5. Known Issues

Item/Category	Brief Description
/	/

6. Functions

Basic Function

Protocol Function

TCP/UDP	NITZ	PING	NTP	LwM2M	MQTT	MQTTS	SSL/TLS	CoAP
Y	Y	Y	Y	Y	Y	Y	Y	Y
CoAPS	HTTP	HTTPS						
Y	Y	Y						

Special Function

DFOTA	PSM	QuecOpen®
Y	Y	Y

NOTES

1. Y means the firmware supports this function.
2. N means the firmware does not support this function.