How to Upgrade the Router Firmware and Module Firmware over the Web GUI?

Steps
<mark>Router Firmware</mark>

1. Log in the LTE5398-M904 as "admin".

2. Go to Firmware Upgrade (Maintenance > Firmware Upgrade > Upgrade Firmware). Specify the router firmware file. Upgrade the file.

OR

Online Firmware Upgrade>Check for Latest Firmware Now

(in this example, it upgrades from V1.00(ABQV.3)C0>>> V1.00(ABQV.4)C0)

Module Firmware

3. Go to Module Upgrade (Maintenance > Firmware Upgrade >
Module Upgrade).

-Check the current firmware version(EG18EAPAR01A08M4G before update)

-Select the correct file for updating(Update_EG18EAPAR01A08M4G-R01A12M4G.zip)

-Click button [Upload] to start to update

-process take around 20 mins, PLEASE DO NOT interrupt during the process and
make sure the power is stable while it is updating.

It will automatically be redirected to login page after finishing updating.

4. After upgrade

-Check the current firmware version should be EG18EAPAR01A12M4G